
Lithium-Ion Battery Fire Investigations
October 2026

Year to date, there have been 52 fires investigated, where a lithium-ion battery was found in the area of origin. Micro Mobility make up the highest number of incidents year-to-date.

Type of Device Powered



Name of Product:
Bose S1 Pro &S1 Pro+ Bluetooth Speaker System

Hazard:
The recalled lithium-ion battery packs can overheat and ignite, posing a risk of injury from fire and overheating hazards..

Remedy:
Consumers should remove the recalled battery packs installed in any S1 Pro and S1 Pro+ Portable Bluetooth Speaker Systems and stop using the battery packs immediately. Once the battery pack is removed, consumers may continue to use their S1 Pro and S1 Pro+ Portable Bluetooth Speakers while connected to AC power.


Recall Date:
November 5, 2026

Units:
About 634,759

U.S. Consumer Product Safety Commission



Structure Type



FIRES AND EMERGENCIES

If a battery overheats or you notice an odor, change in shape/color, leaking, or odd noises from a device, stop using immediately. If safe to do so, move the device away from anything that can catch fire and call 911.

Lithium-Ion batteries are known to unexpectedly re-ignite minutes, hours, and even days after all visible fire has been put out.

If you observe a lithium-ion battery fire, leave the area, CLOSE the door, and call 911 immediately.

Water and fire extinguishers do not work on lithium-ion battery fires.

Source: Connecticut Vision Zero